

Product Discontinuance Notice - PDN 24 0081 Rev. A

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of Select 200mm (8 inch) Products Bumped at Amkor Technology Korea

Publication Date: 17-Dec-2024

Last Time Buy Date: 26-Aug-2025

Last Time Ship Date: 26-Feb-2026

Revision Description:

Remove parts.

Reason For Discontinuance

Loss of manufacturing capability due to ATK5 bump site closure.

Comments

This message is in reference to PDN 24_0081 related to a bump plant closure at Amkor Technology Korea (ATK5). This closure includes the End of Life (EOL) of the 200mm (8 inch) Bump line impacting products you may be using. ADI does not obsolete parts that still have customer demand unless driven by exceptional circumstances and recognizes that customers value the reliability of long-term production assurance.

In this particular case, ADI is taking special measures to support customers with the following actions:

-ADI has initiated procuring additional inventory in die bank to minimize the impact to you as you asses your requirements Submitting your orders promptly will assist ADI in securing an adequate supply of the necessary components to meet your needs.

Analog.com product pages have links to the PDN under each orderable part number and updates to display alternatives on product pages have been added. We apologize for any inconvenience this product discontinuance may cause and remain committed to minimize impact to you. Feel free to contact your ADI sales representative should you have any questions.

Supporting Documents None

| | For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative | | | | |
|-----------|---------------------------------------------------------------------------------------------------------------------|---------|-----------------------|---------------|----------------------|
| Americas: | PDN_Americas@analog.com | Europe: | PDN_Europe@analog.com | Japan: | PDN_Japan@analog.com |
| | | | | Rest of Asia: | PDN_ROA@analog.com |

| PDN 24_0081 Discontinued Parts Material List | | | | |
|----------------------------------------------|----------------|------------------|--------------------------|----------|
| Model | Product Family | Replacement Part | Pin To Pin Compatible | Comments |
| AD9737ABBCZ | AD9737A | None | N/A | |
| AD9737ABBCZRL | AD9737A | None | N/A | |

Removed Parts Across All Revisions of PDN 24 0081 Notices

| Model | Product Family | Replacement Part | Pin To Pin Compatible | Comments |
|--------------------|----------------|------------------|--------------------------|----------|
| AD5811BCDZ-REEL | DAC-DUMP | None | N/A | |
| AD5816FBCDZ-RL7 | AD5816 | None | N/A | |
| ADP2126ACDZ-1.20R7 | ADP2126 | None | N/A | |

| Appendix A - PDN 24_0081 Revision History | | | | |
|-------------------------------------------|--------------|------------------|--|--|
| Rev | Publish Date | Rev Description | | |
| Rev | 29-Aug-2024 | Initial Release. | | |
| Rev. A | 17-Dec-2024 | Remove parts. | | |

Analog Devices, Inc. Proprietary Information

DocId:3187 Layout Rev:4 Parent DocId:None